

FIG.1




FIG.2A




FIG.2B




FIG.3A





FIG.3B



2/22

FIG.4A




FIG.4B




DIAGRAM IN THE DIRECTION OF ARROW A (TOP PLAN DIAGRAM)

FIG.5A





FIG.5B



4/22

FIG.6A





FIG.6B



5/22

FIG.7A




FIG.7B




DIAGRAM IN THE DIRECTION OF ARROW B (TOP PLAN DIAGRAM)

6/22

FIG.8A




FIG.8B




FIG.8C





FIG.9



7/22

FIG.10




FIG.11




FIG.12





FIG.13


MASS CHANGE WHEN A ROLLER MATERIAL IS SOAKED IN DEVELOPER




9/22

**FIG.14**

MASS CHANGE WHEN A ROLLER MATERIAL IS SOAKED IN DEVELOPER



**FIG.15**



10/22

FIG.16

PARTIALLY ENLARGED DIAGRAM






FIG.17




11/22

FIG.18



12/22

**FIG.19A**



**FIG.19B**




FIG.20




FIG.21




FIG.22




FIG.23




FIG.24





FIG.25



17/22

FIG.26




FIG.27




FIG.28




FIG.29A




FIG.29B




FIG.30




FIG.31A




FIG.31B




FIG.32




FIG.33

